

Supporting Statement

The existing front windows and door of the bungalow are single glazed with soft wood frames. They are in very poor condition, which we have had them repaired several times over the years and replaced twice, but they are now beyond uneconomical repair. This winter we had to have the windows temporarily repaired, because the frames were so rotten even some of the glass fell out. We have had them painted with one coat just to smarten them up, as our plan was to change them this summer. We are losing a lot of heat and energy because of the single glaze and makeup of the windows.

In the row of 7 Bungalows, 5 of which have UPVC double glazed windows and doors. We are one of the two bungalows which hasn't got any fitted. Adjacent bungalows across the road of which are 8 in number are all fitted with white UPVC double glazed windows and doors.

We would like to fit two UPVC double glazed white windows and one UPVC double glazed door, which will match in design, size and colour of the existing windows and doors. This would benefit the look of the property and enhance energy efficiency.

Waste Management Plan

The materials that will be disposed of will be 2 x single glazed windows and 1 x single glazed door. The glass will be separated from the frames. The wood frames will be cut up into small pieces. The glass and wood will be sent to the local recycling centre via Richard Hand Haulage.