## Council of the Isles of Scilly Planning Application

Ref: P/23/011/FUL

## **Consultation Response**

**Date:** 21.02.2023

**Ref:** P/23/011/FUL

Site: Hugh Street Cafe, Hugh Street, St Mary's, Isles Of Scilly, TR21 0LL

**Proposal:** Installation of kitchen extraction and air-conditioning with outlets to the outside wall.

You are being consulted on this application as you may wish to make comments before a decision is made. Should you wish to make any comments on this application, please complete the response form below and return to <a href="mailto:planning@scilly.gov.uk">planning@scilly.gov.uk</a> by **14**th **March 2023** or by post to the Planning Department, Town Hall, The Parade, Hugh Town, St Mary's, Isles of Scilly TR21 0LW.

Link to application: https://www.scilly.gov.uk/planning-application/planning-application-p23011ful

I look forward to receiving your comments in due course. If I have not heard back from you by the **14**<sup>th</sup> **March 2023** then I will assume you have no comments to make.

Consultee Name: Environmental Health: Michael Coates, Head of Regulatory Services, Council of the Isles of Scilly

A BS4142 Noise Assessment should be completed prior to the installation of the new commercial kitchen extract ventilation system and air conditioning units including the external condenser unit. Both have outlets to the outside wall and at times may operate simultaneously. The rating level (LAeq, T) from this fixed plant and machinery, when operating simultaneously, should not exceed the background noise level (LA90,T) at any time when measured at the nearest noise sensitive source.

All ductwork serving the new commercial kitchen extract ventilation system should be fitted with antivibration mounts to minimise vibration at adjacent sensitive premises.

The new commercial kitchen extract ventilation system and air conditioning units/external condenser unit should not be operated before 0800hrs.

## Council of the Isles of Scilly Planning Application

The new commercial kitchen extract ventilation system should be fitted with odour control measures in order to minimise grease and odours from cooking fumes. All equipment should be maintained and serviced as per manufacturer's instructions.

Ref: P/23/011/FUL

Name: Michael Coates

Date: 13th March 2023