RECEIVED

have been installed to take the later scantle

the rear scantle roof, which will be set aside for

some form of extension, There is no consistency in style or scale. The blue line is to indicate the extent of the existing and propsed rear line at



JUN 2021